

QUALITY ALERT

June , 2, 2018

Attention:	Huntington Ingalls Incorporated, Newport News Shipbuilding (NNS) Supply Base
Subject:	Non-Conforming Material, Seamless Inconel (A600) Pipe made to ASTM B167 N06600 Upgraded to MIL-F- 23508E
Purpose	NNS recently identified a concern related to Suppliers that upgrade material from commercial to military specifications.
Background	It is common practice for Navy Suppliers to purchase raw material which meet commercial specification and later upgrade the material to the requirements of a military specification (mil spec). In order for the material to be fully compliant to the mil spec referenced in the purchase order, a review of all material test reports must be accomplished. The original mill test reports must be compared to the additional laboratory test reports used for the upgrade. Suppliers must ensure the material meets all NNS Purchase Order requirements. NNS received notification from Electric Boat, our teaming partner, of a request to approve low carbon content in NICRFE (INCONEL 600) material used to make elbows. After investigation into the application in which the elbows were to be used, the request was denied. Further analysis indicated a breakdown in the Suppliers' review of test report certifications, inconsistencies in the test methods utilized by the independent laboratory, and a lack of record retention in order to validate the test results.
Analysis	The first issue concerns the incomplete review of the mill test report by the Supplier. The material test reports provided by the original mill report were in compliance to the commercial specification (ASTM-B167) but did not meet the carbon content to qualify for MIL-F-23508 Rev E. Despite the low carbon, the material was sent to an independent laboratory (lab) for upgrade testing. The independent lab test report indicated higher carbon content than the original test report. The values indicated by the lab stated that the carbon content with MIL-F-23508 Rev E. The Supplier made the determination that the material was acceptable based solely on the chemical test report provided by the independent lab without comparison to the original mill report.

1) The supplier did not perform a proper review of the original mill test report. The material should not have been sent to the independent lab for upgrade testing due to an already indicated low carbon content condition as required by MIL-F-23508 Rev E. The Supplier did not compare the independent laboratory report to the original mill report, so the difference in carbon content went undetected.

A DIVISION OF HUNTINGTON INGALLS INDUSTRIES

4101 Washington Avenue • Newport News, VA 23607 • Telephone (757) 380-2000 • www.huntingtoningalls.com

NN 20 (REV 7) NNPN 3321060



QUALITY ALERT

June 1, 2018

Analysis	The second issue concerns a failure in the independent lab's practices. Two different test methods resulted in different test results and a faultic base of which were expected. The fault has a faultic base of the base of t
	in different test results, only one of which was reported. The first chemical test utilized the Atomic
	Emission Spectroscopy (AES) method for carbon and sulfur analysis. The test results indicated that the
	carbon content was not compliant with MIL-F-23508 Rev E. The second test, performed by the same lab
	using the preferred Combustion method, yielded carbon content that was compliant. Sample specimens
	and supporting data had not been retained so reverification of the test results was not possible.
	The Supplier has the ultimate responsibility for upgrading material from commercial specifications to
	military specifications. All requirements, such as the specification, attributes included in the test reports
	(i.e. test methods, equipment used and calibration dates), retention periods for records, and physical
	samples identified in the Supplier's purchase order must be flowed down to the laboratory performing
	material testing. The Supplier should also have a process to vet the test laboratories and sub-tier suppliers.
	This Quality Alert is being provided to all NNS Suppliers. No response is required.
Disclaimer:	Any action taken as a result of this letter is not to be interpreted as a basis for a contractual commitment
	binding upon NNS , nor should it be used as a basis for any change in price, delay in delivery, or any other
	modification of NNS purchase order requirements.
Point of Contact	

 Point of Contact
 If you have any questions or concerns with regards to this Alert, please contact Marian Morrow, NNS

 Supplier Quality, email LettersofAdvisement@hii-nns.com
 or phone 757-688-0208.

R.Z. Sisson

R. L. Simpson Manager, NNS Supplier Quality

A DIVISION OF HUNTINGTON INGALLS INDUSTRIES

4101 Washington Avenue
Newport News, VA 23607
Telephone (757) 380-2000
www.huntingtoningalls.com

NN 20 (REV 7) NNPN 3321060